

**NZ 62(T)/23      NEW ZEALAND - North Island - East Coast - Waiheke Island -Spray Rock. Danger Buoy**

1. The Spray Rock isolated danger buoy FI(2)5s2M in position 36° 45'.43S., 175° 08'.06E., has been reported as missing.
2. Mariners are advised to exercise caution when navigating in the area.

**Charts temporarily affected:    NZ 53, NZ 532, NZ 533, NZ 5324**

Auckland Transport  
HITS 5324/127