

NZ 28(P)/24 NEW ZEALAND - North Island - East Coast - Napier Harbour. Aids to Navigation

1. Mariners are advised of changes to current charted aids to navigation. The most significant changes are to the light sector arcs:

<i>Int. K No.</i>	<i>Name</i>	<i>Description</i>	<i>Sectors</i>	<i>Position</i>
3982.5	Approach Dir Lt 183°	DirWRG.7m11M	Iso G 179°-180° (1°) Oc G 180°-181° (1°) F G 181°-182° (1°) F W 182°-184° (2°) F R 184°-186° (2°) Oc R 186°-188° (2°) Iso R 188°-189° (1°)	39° 28'.674S., 176° 54'.532E.
3983.15	Inner Directional Light Dir Lt	DirWRG.28m11M	Oc G 107°-108° (1°) F G 108°-110° (2°) Oc W 110°-111° (1°) F W 111°-113° (2°) Oc W 113°-114° (1°) F R 114°-116° (2°) Oc R 116°-117° (1°)	39° 28'.427S., 176° 55'.327E.

2. Mariners are advised to exercise caution when navigating in the area.

3. Charting action will take place in due course.

Charts affected: NZ 5612, NZ 561

NZ Light List: 3982.5, 3983.15

Port of Napier Ltd.
 HITS 5612/141