

NZ 55(P)/24 NEW ZEALAND - South Island - East Coast - Otago Harbour. Aids to Navigation

1. Mariners are advised that the light characteristics of the lateral marks in Upper Harbour, Victoria Channel and Dunedin Wharves have been altered.
2. Mariners are advised to exercise caution when navigating in the area.
3. Charting action will take place in due course.

Chart affected: NZ 6612

NZ Light List: 4373.3 to 4375.1

Port Otago Limited
HITS 6612/351