

NZ 63(T)/24 NEW ZEALAND - North Island - West Coast - South Taranaki Bight. Aid to Navigation

1. Mariners are advised that the FPSO Raroa Racon in position 39°58'.36S., 173°17'.86E. is reported as temporarily failing to transmit signals.
2. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 45, NZ 48, NZ 14600 (INT 600), NZ 14601 (INT 601)

NZ Light List: 4084.75

OMV New Zealand Limited
HITS 45/1097