

1. Dredging works are being conducted in the dredged areas between 'A' Beacon, 37°36'.08S., 176°11'.00E and Town Reach Beacon, 37°39'.96S., 176°10'.59E, until further notice.
2. A lit starboard lateral buoy, *Iso.G.2s*, has been deployed in position 37°39'.299S., 176°10'.590E, until further notice.
3. Additional aids to navigation may be altered as part of these works.
4. A temporary extension to the spoil grounds 'D' and 'G' is in place until further notice. The new extension is bounded by the following positions:
 - (a) 37°36'.718S., 176°11'.537E.
 - (b) 37°37'.859S., 176°12'.986E.
 - (c) 37°36'.706S., 176°14'.421E.
 - (d) 37°35'.566S., 176°12'.971E.
5. Contact the harbourmaster for the most up to date information:
Ph: 07 572 7549
Email: Port.Control@port-tauranga.co.nz
6. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 541, NZ 5413, NZ 5411, NZ 5412

Port of Tauranga
HITS 5412/440