

NZ 76(T)/26 NEW ZEALAND - North Island - East Coast - Tauranga Harbour. Dredging Works, Aids to Navigation and Spoil Ground.

1. Former notices - NZ 25(T)/26 and NZ 69(T)/26 are cancelled.
- * 2. A lit starboard lateral buoy, *Iso.G.2s*, has been deployed in position 37°39'.296S., 176°10'.592E., until further notice.
- * 3. A lit yellow buoy, *Fl.Y.5s*, has been deployed in position 37°40'.089S., 176°10'.569E., until further notice.
4. Additional aids to navigation may be altered as part of these works.
- * 5. Dredging works are being conducted in the dredged areas between 'A' Beacon, 37°36'.08S., 176°11'.00E., and a lit yellow buoy, 37°40'.09S., 176°10'.57E., until further notice.
6. A temporary spoil ground is in place until further notice and bounded by the following positions:
 - (a) 37°36'.718S., 176°11'.537E.
 - (b) 37°37'.859S., 176°12'.986E.
 - (c) 37°36'.706S., 176°14'.421E.
 - (d) 37°35'.566S., 176°12'.971E.
7. Contact the harbourmaster for the most up to date information:
Ph: 07 572 7549
Email: Port.Control@port-tauranga.co.nz
8. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 541, NZ 5411, NZ 5412, NZ 5413

Port of Tauranga
HITS 5412/440, HITS 5412/441, HITS 5412/442