

28 February 2000

NZ 92/00 SOUTH PACIFIC – New Zealand to Hawaii – Submarine cable

Chart NZ 14051 (INT 51) [44/00]

Insert	submarine cable from W. border at: and joining positions	04° 50'.0N., 05° 35'.7N., 07° 09'.0N., 08° 31'.9N., 09° 49'.7N., 11° 46'.0N., 18° 38'.9N., 19° 16'.2N., 20° 00'.0N.,	163° 43'.8W., 162° 49'.0W., 161° 43'.5W., 161° 07'.9W., 161° 17'.1W., 158° 37'.2W., 158° 10'.0W., 155° 54'.2W.
--------	---	--	---

Land Information New Zealand