


**NZ 50/04 SOUTH PACIFIC – Fiji Islands to Hawaii – Submarine Cable.**

**Chart NZ 14604 ( INT 604 ) [ 40/04 ]**

Insert submarine cable, joining positions

- 18° 10'.0S., 178° 28'.1E.
- 18° 17'.0S., 178° 25'.2E.
- 18° 25'.8S., 178° 21'.3E.
- 18° 46'.0S., 178° 00'.0E.
- 18° 51'.2S., 177° 43'.6E.
- 18° 50'.5S., 177° 29'.1E.
- 18° 48'.6S., 177° 27'.4E.
- 18° 28'.4S., 177° 03'.6E.
- 18° 17'.1S., 176° 55'.7E.
- 18° 10'.6S., 176° 53'.3E.
- 18° 01'.9S., 176° 46'.9E.
- 17° 46'.2S., 176° 31'.9E.
- 17° 30'.2S., 176° 21'.1E.
- 17° 20'.0S., 176° 18'.5E.
- 16° 48'.7S., 176° 10'.7E.
- 16° 36'.2S., 176° 05'.8E.
- 16° 28'.1S., 176° 07'.5E.
- 16° 00'.0S., 176° 20'.0E.
- 14° 57'.8S., 176° 47'.4E.
- 14° 00'.0S., 177° 15'.4E.
- 13° 00'.6S., 177° 49'.0E.
- 12° 32'.5S., 177° 50'.0E.
- 12° 00'.0S., 177° 43'.2E.
- 11° 36'.1S., 177° 43'.8E.
- 10° 56'.6S., 177° 54'.0E.
- 10° 43'.0S., 177° 56'.8E.
- 9° 57'.4S., 178° 12'.3E.
- 9° 31'.7S., 178° 29'.6E.
- 8° 59'.2S., 178° 59'.3E.
- 8° 30'.5S., 179° 33'.0E.
- 7° 57'.6S., 179° 58'.8W.

Fiji Notice 6/01  
 NI 17/2004



Issued as a guide to chart correction.

Use in conjunction with the appropriate NZ Notice to Mariners.

**LAST CORRECTION**

**NZ NTM No.**

**CHART No.**

**NZ 40/04**

**NZ 50/04**

**NZ 14604 (INT 604)**