

IV

**NZ 56(P)/22 NEW ZEALAND - South Island - East Coast - Banks Peninsula. Rocks**

1. A recent survey (2021) in the vicinity of Banks Peninsula indicates changes to charted features and depths. The most significant changes are as follows:

	<i>Position</i>	<i>Depth</i>	<i>Feature</i>
(a)	43°36'.338S., 172°51'.824E.	8.3	Underwater Rock
(b)	43°36'.380S., 172°51'.772E.	4	Underwater Rock
(c)	43°36'.939S., 172°54'.046E.	9.3	Underwater Rock
(d)	43°41'.865S., 173°06'.642E.	3.4	Underwater Rock
(e)	43°44'.014S., 173°08'.036E.	7.2	Underwater Rock
(f)	43°46'.685S., 173°07'.968E.	8	Underwater Rock
(g)	43°50'.052S., 173°06'.248E.	-1.6	Underwater Rock
(h)	43°51'.319S., 172°45'.484E.	1.6	Underwater Rock
(i)	43°52'.045S., 172°47'.529E.	1	Underwater Rock
(j)	43°52'.260S., 172°46'.838E.	3	Underwater Rock
(k)	43°52'.433S., 173°02'.108E.	0.9	Underwater Rock
(l)	43°52'.856S., 172°49'.200E.	4.5	Underwater Rock
(m)	43°53'.474S., 172°50'.047E.	0.4	Underwater Rock
(n)	43°53'.803S., 172°53'.963E.	7.2	Underwater Rock

2. Mariners are advised to exercise caution when navigating in the area.
3. Charting action will take place in due course.

**Charts affected: NZ 632, NZ 6321, NZ 6324**

Discovery Marine Ltd.  
HITS 632/23