

6 March 2000

NZ 102/00 SOUTH PACIFIC – New Zealand to Hawaii – Submarine cable

Chart NZ 14052 (INT 52) [74/00]

| | | | | |
|--------|------------------------------------|---|---------------|---------------|
| Insert | submarine cable, joining positions | : | 12° 53'.6S., | 167° 04'.2W. |
| | | | 10° 50'.3S., | 166° 46'.7W. |
| | | | 07° 19'.9S., | 166° 00'.8W. |
| | | | 05° 02'.0S., | 165° 56'.9W. |
| | | | 02° 45'.3S., | 166° 09'.2W. |
| | | | 02° 00'.0S., | 166° 00'.5W. |
| | | | 01° 20'.0S., | 165° 48'.3W. |
| | | | 00° 30'.0S., | 165° 20'.3W. |
| | | | 00° 00'.3S., | 165° 07'.6W. |
| | | | 02° 07'.3N., | 165° 17'.1W. |
| | | | 02° 36'.8N., | 164° 44'.7 W. |
| | | | 03° 10'.0N., | 164° 33'.7W. |
| | | | 05° 35'.7N., | 163° 43'.8W. |
| | | | 07° 09'.0N., | 162° 49'.0W. |
| | | | 08° 31'.9N., | 161° 43'.5W. |
| | | | 09° 49'.7N., | 161° 07'.9W. |
| | | | 11° 46'.0N., | 161° 17'.1W. |
| | | | 18° 38'.9N., | 158° 37'.2W. |
| | | | 19° 16'.2N., | 158° 10'.0W. |
| | | | 20° 00'.5 N., | 155° 54'.2W. |