

NZ 378 NEW ZEALAND – North Island – East Coast – Bay of Plenty – Harbour Limits.

Chart NZ 541 [220/00]

Delete	pecked line, harbour limit, from shoreline at	(a) 37° 44'.60S., 176° 24'.15E.
	to	(b) 37° 41'.00S., 176° 26'.00E.
	to eastern border at	(c) 37° 47'.80S.
	legends, Central Bay of Plenty Harbour Limit,	(d) 37° 42'.60S., 176° 25'.00E.
		(e) 37° 46'.00S., 176° 42'.20E.

Chart NZ 542 [338/00]

Delete	pecked line, harbour limit, from shoreline at	(a) 37° 44'.60S., 176° 24'.15E.
	to	(b) 37° 41'.00S., 176° 26'.00E.
	to	(c) 37° 50'.83S., 176° 58'.10E.
	to shoreline at	(d) 37° 59'.40S., 177° 19'.32E.
	legends, Central Bay of Plenty Harbour Limit,	(e) 37° 42'.83S., 176° 25'.17E.
		(f) 37° 46'.10S., 176° 42'.32E.
		(g) 37° 54'.25S., 177° 06'.30 E.

Bay of Plenty Regional Council

NZ 379 NEW ZEALAND – South Island – East Coast – Lyttelton Harbour – Berth Designations

Chart NZ 6321 (plan , Port of Lyttelton) [NE Jun 00]

Substitute	designation of berth, A , for B	43° 36'.353S., 172° 43'.315E.
	designation of berth, B , for A	43° 36'.342S., 172° 43'.304E.

Lyttelton Port Company Ltd.

NZ 380 SOUTH PACIFIC – Polynesie Francaise – Archipel des Tuamotu – Fakarava – Light Established.

Chart NZ 14061 (INT 61) [374/00]

Insert	★	16° 04'.0S., 145° 41'.4W.
--------	---	---------------------------

Chart NZ 14606 (INT 606) [311/00]

Insert	★	16° 04'.0S., 145° 41'.4W.
--------	---	---------------------------

Chart NZ 14607 (INT 607) [374/00]

Insert	★	16° 04'.0S., 145° 41'.4W.
--------	---	---------------------------

French Notice 00 37 38

NZ 381(T)/00 NEW ZEALAND – North Island – East Coast – Bay of Islands – Orongo Bay – Obstruction.

An obstruction, drying at Low Water Springs, exists in Orongo Bay, in position 35° 17'.04S., 174° 08'.20E.

Chart temporarily affected – NZ 5124

Mr. Murray Campbell