

NEW ZEALAND NOTICES TO MARINERS

Notices

NZ 165 – 172

© Crown Copyright 2009. All rights Reserved. Permission is not required to make analogue copies of these Notices but such copies are not to be sold.

CONTENTS

- I [Explanatory Notes.](#)
- II [New Zealand Notices to Mariners.](#)
- III [Corrections to New Zealand Light List.](#)
- IV [Corrections to Sailing Directions and New Zealand Publications.](#)
- V [Navigational Warnings. \(NAVAREA XIV\)](#)
- VI [Corrections to Admiralty List of Radio Signals.](#)

New Zealand Notices to Mariners are the authority for correcting New Zealand charts within the New Zealand area of charting responsibility as shown in Notice No. 1.

Mariners are requested to immediately inform Land Information New Zealand, PO Box 5501 Lambton Quay, Wellington 6145, New Zealand Phone : 0800 665 463 or (04) 460-0110 Fax: (04) 460-0161 or e-mail: info@linz.govt.nz, of the discovery of new or suspected dangers to navigation, or shortcomings in charts and publications. A copy of a Hydrographic Note, a convenient form on which to send such information, is included at the end of Section VI of the Fortnightly Notices to Mariners.

Changes or defects in aids to navigation should be reported to the Rescue Coordination Centre New Zealand (RCCNZ) via the nearest New Zealand Coastal Maritime Radio Station Phone : (04) 577-8030 Fax : (04) 577-8038 or (04) 577-8041 e-mail: rccnz@maritimenz.govt.nz.

Copies of these Notices can be obtained from Land Information New Zealand, Maritime New Zealand, Principal Chart Agents at the major ports of New Zealand and the Internet: www.linz.govt.nz

EXPLANATORY NOTES

Charts. The notices in Section II give instructions for the correction of charts. Geographical positions refer to the largest scale chart unless otherwise stated. They are normally given in degrees, minutes and decimals of a minute, but may occasionally quote seconds for convenience when plotting from the graduation of some older-style charts. Bearings are true reckoned clockwise from 000° to 359°; those relating to lights are given as seen by an observer from seaward. Symbols referred are those shown in publication Chart 5011 (*INT 1*) Symbols and Abbreviations used on Admiralty Charts, published by the United Kingdom Hydrographic Office.

Alterations to depth contours, deletion of depths to make way for new detail, etc. are not mentioned unless they have some navigational significance.

Blocks or notes accompanying notices in Section II are placed after Section VI.

Temporary and Preliminary Notices. These are indicated by (T) or (P) after the notice number. A list of (T) and (P) Notices in force is published in the fortnightly Editions of Notices to Mariners. Charts are not corrected for them before issue; they should be corrected in pencil on receipt.

Light Lists. The detailed correction to the Light List is given in Section III and may not be published in the same edition as the chart correcting notice. The entire entry for each light is printed, and an asterisk (*) is shown under the column which contains an amendment. In the case of a new light, an asterisk (*) appears under all the columns. New and extensively altered entries are intended to be pasted in. It is recommended that a manuscript entry be made for all shorter corrections.

It is emphasized that the List of Lights is the authority for lights and that many alterations, especially those of a temporary but operational nature, may only be promulgated as corrections to the List of Lights.

Radio Signals. When radio signals are affected by a notice the Admiralty List of Radio Signals reference number is quoted. The detailed correction to the List of Radio Signals is given in Section VI and may be published in a later edition than the chart correcting notice.

Sailing Directions. Corrections to Sailing Directions are given in Section IV. It is recommended that such corrections be kept together in a file with the latest list of those in force on top. The file can then be consulted when using the parent book to see if any notices affecting the area under consideration are extant.

Corrections should not be pasted into the parent book or Supplement as corrections may be issued between closing date and issue of a new Supplement. These will be embodied in the text of the following Supplement. A summary of corrections in force will be issued in Section IV of the Fortnightly Edition at monthly intervals.

New Zealand Publications. Corrections to New Zealand Publications are given in Section IV.

Correction of Charts and Publications by the User. New Zealand Notices to Mariners contain important information and should be used to keep the specified charts and books up to date.

THE USE OF CHARTS AND ASSOCIATED PUBLICATIONS

Reliance on Charts and Associated Publications. While every effort is made to ensure the accuracy of the information on New Zealand charts and other publications, it should be appreciated that it may not always be complete and up to date. The mariner must be the final judge of the reliance to be placed on the information given, bearing in mind their particular circumstances, local pilotage guidance and the judicious use of available navigational aids.

Charts. Charts should be used with prudence: there are areas where the source data are old, incomplete or of poor quality. The mariner should use the largest scale appropriate for his particular purpose; apart from being the most detailed, the larger scales are usually corrected first. When extensive new information (such as a new hydrographic survey) is received, some months may elapse before it can be fully incorporated in published charts. On small scale charts of ocean areas where hydrographic information is, in many cases, still sparse, charted shoals may be in error as regards position, least depth and extent. Undiscovered dangers may exist, particularly away from well-established routes.

Further guidance. The Mariner's Handbook (NP 100) gives a fuller explanation of the limitations of charts. All users should study it in their own interest.

II

NUMERICAL INDEX OF CHARTS AFFECTED (NZ NTM Edition No.17 dated 21 August 2009)

NZ Chart No.	NZ Notices	INT Chart No.	Notices
NZ 521 NZ 632 NZ 5214 NZ 5322 NZ 5323 NZ 6153 NZ 6154 NZ 6321	NZ 170(T) NZ 172(T) NZ 170(T), 171(T) NZ 167, 168 NZ 167 NZ 169 NZ 169 NZ 172(T)		
ENC Cell	Notices		
NZ405411 NZ405413 NZ462121 NZ462122 NZ505412	NZ 166 NZ 166 NZ 165 NZ 165 NZ 166		

II

NEW ZEALAND TEMPORARY AND PRELIMINARY NOTICES IN FORCE

(NZ NTM Edition No.17 dated 21 August 2009)

NZ Notice	T/P	Charts Affected	Locality and Subject
		NZ Chart, INT Chart, ENC Cell	
133/01	T	NZ 6612	Otago Hr.: Shoaling
180/03	T	NZ 6154	Picton Hr.: Shoal Depths.
129/04	T	NZ 52, 53, 522, 5227	Hauraki Gulf: Dredging Operations
194/04	P	NZ 46, 48, 61, 463, 614, 6151, 6152, 6153, 6154	Marlborough Sounds: Use of Automated Navigation Systems
110/05	T	NZ 8248	Tonga: Light Unlit
161/05	P	NZ 4633, 4634	Wellington Hr.: Navigation Safety Bylaw
173/05	T	NZ 53, 54, 531, 534, 5318	Whitianga Hr.: Sandbar
176/06	T	NZ 23, 26, 56, 14060, 14600, INT 60, 600, 640	N. Island, E. Coast: Scientific Instruments
177/06	T		Indian Ocean: Operation 'Enduring Freedom'
205/06	T	NZ 532, 5324	Tamaki Strait: Motuihe Is.: E. Cardinal Lt Beacon
213/06	P	NZ 6153, 6154	Picton Hr.: Lights
244/06	T	NZ 23, 25, 63, 64, INT 640, 648	Lyttelton Hr.: Waverider Buoy
37/07	T	NZ 53, 532, 533, 5327	Firth of Thames: Moorings, Research Instruments
63/07	T	NZ 4633	Wellington Hr.: Race Marker Buoys
219/07	P	NZ 54, 542	Bay of Plenty, Opoitiki: Fish Haven
20/08	T	NZ 54, 542	Bay of Plenty: Research Instruments
35/08	T	NZ 614	Motueka River: Current Meter
91/08	P	NZ 4424	W. Coast, Taharoa Hr.: Hr. Limits
131/08	T	NZ 68, 69, 681	Foveaux Strait, Ruapuke Is.: Seabed Obstruction
132/08	T	NZ 14051, 14052, 14060, 14061, 14604, 14605, 14606, 14607, 14629, INT 51, 52, 60, 61, 604, 605, 606, 607, 629	North, South Pacific Ocean: ATLAS Buoys
216/08	T	NZ 45, 48	S. Taranaki Bight: Drilling Operations
243/08	P	NZ 5612	Napier Hr.: New Wharf Development
244/08	P	NZ 632, 6321	Banks Peninsula: Mussel Farms
258/08	T	NZ 63, 64	Lyttelton Hr.: Works in Progress
259/08	T	NZ 5225	Great Barrier Island: Marine Farm
262/08	T	NZ 2411	Snares Islands/Tini Heke: Seabed Obstruction
39/09	T	NZ 4314, 4315	Manukau Hr.: Light Beacons, Buoys
48/09	T	NZ 6321	Sumner Head: Buoy
95/09	T	NZ 521	Bream Bay: Scientific Moorings
96/09	T	NZ 532, 5321, 5322	Hauraki Gulf: Works in Progress
117/09	T	NZ 25, 64, 66, 661	Cape Saunders Southwards: Waverider Buoy
118/09	T	NZ 8275 (T 8275)	Tonga, Nuku'alofa Hr.: Light
123/09	T	NZ 4634, NZ546342	Wellington Hr.: Light, Beacon
138/09	T	NZ 23, 25, 62, 63, INT 640, 648	Kaikoura Peninsula: Scientific Moorings
139/09	T	NZ 845, 14630, 14631, INT 630, 631	Nuie Is: Lights
143/09	T	NZ 5322, 5323, NZ505322	Auckland Hr.: Vertical Clearance
149/09	T	NZ 43, 48, 443, NZ300443	N. Taranaki Bight: Underwater Operations
155/09	T	NZ 5125	Bay of Islands: Light
156/09	T	NZ 7142	Greymouth Hr.: Depths
162/09	T		Maritime Safety Broadcasts
164/09	T	NZ 4314, NZ404314	Manukau Hr.: Depths
171/09	T	NZ 5214	Marsden Point: Works in Progress

NZ 165/09 NEW ZEALAND PUBLICATIONS – (1) New Zealand ENC's Published.

<i>ENC Cell</i>	<i>Released</i>	<i>Title</i>
NZ462122	August 2009	NZ462122 – NZ6212 - South Island – North East Coast – Kaikoura Peninsula

(2) New Zealand ENC Permanently Withdrawn

<i>ENC Cell</i>	<i>On Publication of ENC Cell</i>	<i>Date</i>
NZ462121	NZ462122	August 2009

README.TXT File

The README.TXT file located within the ENC_ROOT folder of an ENC exchange set contains important safety related information. This file is updated on a regular basis and should be consulted to ensure that all related issues are taken into consideration. The latest README.TXT file is also located on the LINZ website www.linz.govt.nz/hydro/enc/readme

Use of Electronic Navigational Charts

For compliance with New Zealand legal requirements for nautical charts and publications please refer to Maritime Rules Part 25, as supported by Maritime New Zealand Marine Guidance Notice 8 "Use of Electronic Charts, ECDIS and ENC's in NZ" available from the Maritime New Zealand website www.mnz.govt.nz/Commercial/Shipping-safety/Safety-updates/Guidance-notices.asp.

Land Information New Zealand
 NI 171/2009

NZ 166/09 NEW ZEALAND PUBLICATIONS – New Zealand ENCs to be Published Shortly.

ENC Cell Title

NZ405411 NZ405411 – NZ5411 - North Island - East Coast - Tauranga Harbour - Katikati Entrance to Mount Maunganui

NZ405413 NZ405413 – NZ5413 - North Island - East Coast - Approaches to Tauranga

NZ505412 NZ505412 – NZ5412 - North Island - East Coast - Port of Tauranga

Land Information New Zealand
NI 172/2009

NZ 167/09 NEW ZEALAND – North Island – East Coast – Auckland Harbour – Calliope Wharves – Light Beacon, Depth.

Chart NZ 5322 [179/08]

Insert depth, 4₈ enclosed by 5m contour 36° 49'.80S., 174° 46'.96E.

Delete  Q(9)15s (a) 36° 49'.78S. 174° 46'.91E.
YBY

5m contour, extending E of (a) above

Chart NZ 5322 (plan, Calliope Wharves)

Insert depth, 4₈ enclosed by 5m contour 36° 49'.798S., 174° 46'.956E.

Delete  Q(9)15s3m3M 36° 49'.783S., 174° 46'.905E.
YBY

depth, 4₃ (a) 36° 49'.786S., 174° 46'.927E.
depth, 3₄ (b) 36° 49'.800S., 174° 46'.961E.
5m contour, encompassing (a) & (b) above


Chart NZ 5323 [155/08]

Insert depth, 4₈ enclosed by 5m contour 36° 49'.80S., 174° 46'.96E.


Delete  Q(9)15s (a) 36° 49'.78S., 174° 46'.91E.
YBY

5m contour, extending E of (a) above


New Zealand Defence Force
NZ Light List K3769
NI 150/2009



Issued as a guide to chart correction.		Use in conjunction with the appropriate NZ Notice to Mariners.
LAST CORRECTION	NZ NTM No.	CHART No.
NZ 179/08	NZ 167/09	NZ 5322



Issued as a guide to chart correction.		Use in conjunction with the appropriate NZ Notice to Mariners.
LAST CORRECTION	NZ NTM No.	CHART No.
NZ 179/08	NZ 167/09	NZ 5322




Issued as a guide to chart correction.		Use in conjunction with the appropriate NZ Notice to Mariners.
LAST CORRECTION	NZ NTM No.	CHART No.
NZ 155/08	NZ 167/09	NZ 5323

NZ 168/09 NEW ZEALAND – North Island – East Coast – Auckland Harbour – Buoy.

Chart NZ 5322 [167/09]

Move  from: 36° 50'.62S., 174° 47'.60E.
 Y to: 36° 50'.65S., 174° 47'.90E.

Auckland Regional Council
 NI 4/2009



<i>Issued as a guide to chart correction.</i>		<i>Use in conjunction with the appropriate NZ Notice to Mariners.</i>
LAST CORRECTION	NZ NTM No.	CHART No.
NZ 167/09	NZ 168/09	NZ 5322



NZ 169/09 NEW ZEALAND – South Island – North Coast – Picton Harbour – Light, Beacon.

Chart NZ 6153 [121/07]

Substitute Fl.R.3s5m5M for Q.R.2m5M 41° 16'.91S., 174° 00'.71E.
W R



Chart NZ 6153 (Continuation Plan)

Substitute Fl.R.3s5m5M for Q.R.2m5M 41° 16'.91S., 174° 00'.71E.
W R


Chart NZ 6154 (Plan, Picton Harbour) [209/08]

Substitute Fl.R.3s5m5M for Q.R.2m5M 41° 16'.910S., 174° 00'.710E.
W R

Marlborough District Council
NZ Light List K4256.7
NI 170/2009



Issued as a guide to chart correction. Use in conjunction with the appropriate NZ Notice to Mariners.			Issued as a guide to chart correction. Use in conjunction with the appropriate NZ Notice to Mariners.		
LAST CORRECTION	NZ NTM No.	CHART No.	LAST CORRECTION	NZ NTM No.	CHART No.
NZ 121/07	NZ 169/09	NZ 6153	NZ 121/07	NZ 169/09	NZ 6153



<i>Issued as a guide to chart correction.</i>		<i>Use in conjunction with the appropriate NZ Notice to Mariners.</i>
LAST CORRECTION	NZ NTM No.	CHART No.
NZ 209/08	NZ 169/09	NZ 6154

**NZ 170(T)/09 NEW ZEALAND – North Island – East Coast – Whangarei Approach Channel –
Works Complete.**

Former notice – NZ 157(T)/09 is cancelled.

Cancel this notice on receipt.

Charts formerly affected – NZ 521 – NZ 5214

Northland Regional Council
NI 166/2009

NZ 171(T)/09 NEW ZEALAND – North Island – East Coast – Marsden Point – Works in Progress.

Former notice – NZ 45(T)/09 is cancelled.

1. Until the end of September 2009 construction work is being carried out on a new jetty extension at Marsden Point Oil Refinery, Jetty No.2. Work involves a heavy lift crane mounted on the barge *BK Subritzky*.
2. Mariners are advised to give the construction area a wide berth and reduce speed to a minimum so as to have no vessel wake when passing during heavy lift operations.
3. Local navigation information will be broadcast by Whangarei Harbour Radio VHF Ch. 19 and Whangarei Coastguard VHF Ch. 64 during heavy lift operations.

Chart temporarily affected – NZ 5214

Northland Regional Council
NI 167/2009

**NZ 172(T)/09 NEW ZEALAND – South Island – East Coast – Banks Peninsula – Lyttelton Harbour –
Buoys, Light.**

Former notice – NZ 237(T)/08 is cancelled.

Cancel this notice on receipt.

Charts formerly affected – NZ 632 – NZ 6321

McConnell Dowell Constructors Ltd
NI 173/2009

III

CORRECTIONS TO NEW ZEALAND LIGHT LIST

(NZ NTM Edition No.17 dated 21 August 2009)

NEW ZEALAND NAUTICAL ALMANAC 2009/10 LIGHT LIST SECTION

3769 Delete from list

4256.7	- Shelly Beach	41 16.91 174 00.71	FI R 3s	5	5	White metal post	fl 0.3
			*	*			*

(NI 150, 170/2009)

IV

CORRECTIONS TO PUBLICATIONS

(NZ NTM Edition No.17 dated 21 August 2009)

Nil

V

NAVIGATIONAL WARNINGS

Navarea XIV warnings in force 19 August 2009

NAVAREA XIV

(South West Pacific)

- 040/09 SOUTH PACIFIC OCEAN. CHART INT 61
1. Hazardous Operations Space Debris. 240613 UTC to 240752 UTC and 250550 UTC to 250726 UTC and 260525 UTC to 260705 UTC Aug 09 in area bounded by:
 - A. 42-59S 171-56W
 - B. 37-18S 161-52W
 - C. 30-02S 152-30W
 - D. 21-26S 143-59W
 - E. 23-09S 141-47W
 - F. 29-56S 148-15W
 - G. 38-23S 158-56W
 - H. 43-06S 167-03W
 - I. 44-49S 170-49W

Cancel this Message 260805 UTC Aug

VI

CORRECTIONS TO ADMIRALTY LIST OF RADIO SIGNALS

(NZ NTM Edition No.17 dated 21 August 2009)

VOLUME 6, PART 4, NP 286(4), 2009/10

Published BA Wk 30/09

(Last Amendments: Weekly Edition No. 31 dated 30 July 2009)

PAGE 96, AUSTRALIA, YAMBA, N.S.W., Pilots and Port, PROCEDURE.

Delete section (3) and replace by:

(3) **Pilot boards** in the following positions:

(a) North: 29°25'·17S 153°23'·24E

(b) South: 29°26'·02S 153°22'·74E

Australian Notice 14/811/2009, (HH080/021/21 - E31), 32/09

(NI 169/2009)

(BA Wk 32/2009)



HYDROGRAPHIC NOTE

(For instructions, see next page)

LINZ Hydrographic Services
National Office
PO Box 5501
Lambton Quay
Wellington 6145
New Zealand

Tel: 0800 665 463
Fax : +64 4 460 0161
Email: info@linz.govt.nz

Date Ref.No.

Name and address of ship or sender

.....
.....

Tel/Fax/Telex/Email of sender

General locality

Subject

Position. Lat. Long.

Position fixing system used

Datum

Charts affected Edition

Dated

Latest Notice to Mariners held

Publications affected (Edition No. and date of latest supplement, page no, ID no. etc)

Details:

A replacement copy of Chart No.
is required (see Instruction 4).

Signature of observer/reporter

HYDROGRAPHIC NOTE

Forwarding Information for Charts and Hydrographic Publications

Note: An acknowledgement of receipt will be sent and the information then used to the best advantage, which may mean immediate action or inclusion in a revision in due course. When a Notices to Mariners is issued, the sender's ship or name is quoted as authority unless (as sometimes happens) the information is also received in a foreign Notices to Mariners. An explanation of the use of contributions from all parts of the world would be too greater task and a further communication should only be expected when the information is of outstanding value or has unusual features.

INSTRUCTIONS:

1. Mariners are requested to notify LINZ Hydrographic Services, National Office, Land Information New Zealand, PO Box 5501, Lambton Quay, Wellington 6145, New Zealand, when new or suspected dangers to navigation are discovered, changes observed in aids to navigation, or corrections to publications seem to be necessary. The *Admiralty* publication, *The Mariner's Handbook* (NP 100), "Chapter 8", gives general instructions.
2. This form and its instructions have been designed to help both the sender and the recipient. It should be used, or followed, closely, whenever appropriate. Copies of this form may be obtained gratis from LINZ Hydrographic Services at the address above, or in PDF format directly from the LINZ website at www.linz.govt.nz.
3. When a position is defined by sextant angles or bearings (true or magnetic being specified) more than two should be used in order to provide a check. Distances observed by radar should be quoted. However, when there is a series of fixes along a ship's course, only the method of fixing and the objects used need to be indicated. Latitude and longitude should only be used specifically to position the details when they have been fixed by astronomical observations or GPS and a full description of the method, equipment and datum used should be given.
4. A cutting from the largest scale paper chart is the best medium for forwarding details, the alterations and additions being shown thereon in red. When requested, a new copy will be sent in replacement of a chart that has been used to forward information, or when extensive observations have involved defacement of the observer's chart. If it is preferred to show the amendments on a tracing of the largest scale chart (rather than the chart itself) these should be in red as above, but adequate detail from the chart must be traced in black ink to enable the amendments to be fitted correctly.
5. When soundings are obtained, *The Mariners Handbook* (NP 100) should be consulted. The echo sounding trace should be marked with times, depths, etc., and forwarded with the report. It is important to state whether the echo sounder is set to register depths below the surface, or below the keel; in the latter case the vessel's draught should be given. Time and date should be given in order that corrections for the height of the tide may be made where necessary. The make, name, and type of echo sounder set should also be given.
6. Modern echo sounders frequently record greater depths than the set's nominal range, e.g. with a set whose maximum is 500m a trace appearing at 50m may in fact be 550m or even 1,050m. Erroneous deep soundings beyond the sets nominal range can usually be recognised by the following:
 - (a) The trace being weaker than normal for the depth registered
 - (b) The trace appearing to pass through the transmission line
 - (c) The "feathery" nature of the trace.
7. Reports which cannot be confirmed or are lacking in certain details should not be withheld. Shortcomings should be stressed and any firm expectation of being able to check the information on a succeeding voyage should be mentioned.
8. Reports of shoal soundings, uncharted dangers and navigational aids out of order should, at the mariner's discretion, also be made by radio to the nearest coast radio station. The draught of modern tankers is such that any uncharted depth under 30 metres or 15 fathoms may be of sufficient importance to justify a radio message.